



# Bare Fiber Adapter

## **Instrumentation & Network Interconnects**

## **APPLICATIONS**

- Temporarily connect test instruments such as OTDR's, OPM's and VFL's to fiber under test



#### **BENEFITS**

- Provides a fast method of temporarily connecting a fiber under test to a test instrument
- Measure the length of fiber on a spool with an OTDR without having to connectorize the fiber spool
- Measure the optical power present on a fiber without a connector
- Temporarily connect a VFL to a fiber so that the technician can inject visible light onto a fiber that does not have a connector

#### **SPECIFICATIONS**

Fiber Sizes Up to 250 micron acrylic

Connector SC/PC

### ORDERING INFORMATION

CAT. NO. UPC BFA-1 06809