
## **SERVICE BULLETIN**




## Handle Replacement Service Group 49085



Service Part 170230 Handle is being replaced by Service Group Part 49085
To Include:

KEY	PART NO.	DESCRIPTION	QTY.
1	48813	Handle	1
2	48817	Guard	1
3	L084015	Washer	1
4	F018077	Screw	1
5	F021676	Screw	2



Note: This new style handle now has O-ring style pressure and return porting.

## GREENLEE FAIRMONT TEXTRON

Greenlee Textron Inc. / Subsidiary of Textron Inc.

4455 Boeing Drive, Rockford, IL 61109-2988 USA
General Offices: 815/397-7070
Customer Center and Field Service: 800/435-0786
Fax (24 Hours) Customer Center: 800/451-2632 • 815/397-1865
Canada Fax (24 Hour) Customer Center: 800/524-2853

Printed in the U.S.A.